

DO YOU KNOW 4 KEY FACTORS INFLUENCING SCALE ACCURACY?

KILOTECH Easy to use reliable scales



READABILITY

The smallest increment by which the scale's displayed measurement changes as weight is added or removed.



REPEATABILITY

Gauges how consistently a scale displays the exact value when the same weight is placed on it repeatedly.



LINEARITY

Measures how well a scale displays the correct weight value throughout its full capacity range.



REPRODUCIBILITY

Reproducibility assesses a scale's ability to display the correct weight value over time, considering changes in environmental conditions.